

Prebona OdorControl™

Prebona OdorControl – clogged spray bottle

Prebona OdorControl is sold in 500 ml spray bottle. The nozzle of the spray bottle may become clogged. When the nozzle is clogged, it is not possible to use the spray bottle.

The reason for glogged nozzle is the silica particles, which normally are suspended in water. If the silica particles are allowed to dry, they may clog the small opening in the nozzle of the spray bottle. To unclog the nozzle, insert a pin into the the nozzle.



If nozzle of spray bottle with Prebona OdorControl is clogged, insert a pin into the nozzle. This will unclog the nozzle.

Prebona*